

ਵੱਲ

ਪੀ.ਐਸ.ਟੀ. ਮੈਮੋਰੀਅਲ ਸਕੂਲ,  
ਜੰਡ ਸਾਹਿਬ ਰੋਡ, ਘੁੱਦਵਾਲਾ  
ਜ਼ਿਲ੍ਹਾ ਫ਼ਰੀਦਕੋਟ।  
ਨੰ: DB/ 9521

ਮਿਤੀ: 18.02.2025

ਵਿਸ਼ਾ:

ਸਾਲ 2024-25 ਲਈ ਸਕੂਲ ਬਿਲਡਿੰਗ ਸੇਫਟੀ ਸਰਟੀਫਿਕੇਟ ਜਾਰੀ ਕਰਨ ਬਾਰੇ।( ਪੀ.ਐਸ.ਟੀ. ਮੈਮੋਰੀਅਲ ਸਕੂਲ, ਜੰਡ ਸਾਹਿਬ ਰੋਡ, ਘੁੱਦਵਾਲਾ, ਜ਼ਿਲ੍ਹਾ ਫ਼ਰੀਦਕੋਟ)

ਉਪਰੋਕਤ ਵਿਸ਼ੇ ਅੰਕਿਤ ਸਕੂਲ ਦੀ ਇਮਾਰਤ ਦਾ ਬਿਲਡਿੰਗ ਸੇਫਟੀ ਸਰਟੀਫਿਕੇਟ ਸਾਲ 2024-25 ਲੈਣ ਲਈ ਆਪ ਵੱਲੋਂ ਇਸ ਦਫ਼ਤਰ ਵਿਖੇ ਪ੍ਰਾਪਤ ਹੋਇਆ ਹੈ। ਆਪ ਦੇ ਸਕੂਲ ਦੀ ਬਿਲਡਿੰਗ ਦਾ ਉਪ ਮੰਡਲ ਇੰਜੀਨੀਅਰ ਦੇ ਦਫ਼ਤਰ ਵੱਲੋਂ ਵਿਜ਼ੂਅਲੀ ਇੰਸਪੈਕਸ਼ਨ ਕੀਤੀ ਗਈ ਅਤੇ ਉਨ੍ਹਾਂ ਦੀ ਰਿਪੋਰਟ/ਸਿਫਾਰਿਸ਼ ਅਨੁਸਾਰ ਨਿਮ ਨਲਿਖਤ ਨਿਰੀਖਣਾਂ ਅਤੇ ਸ਼ਰਤਾਂ ਅਧੀਨ ਸਾਲ 2024-25 ਦਾ ਸਕੂਲ ਬਿਲਡਿੰਗ ਸੇਫਟੀ ਮਿਤੀ 31-03-2025 ਤੱਕ ਜਾਰੀ ਕੀਤਾ ਜਾਂਦਾ ਹੈ:-

1. ਸਕੂਲ ਕੋਲ ਕਿਸੇ ਅਣਸੁਖਾਵੀਂ ਆਪਦਾ ਨਾਲ ਨਜਿੱਠਣ ਲਈ ਯੋਜਨਾ ਹੋਣੀ ਚਾਹੀਦੀ ਹੈ, ਜਿਸ ਵਿੱਚ ਐਮਰਜੈਂਸੀ ਦੌਰਾਨ ਬੱਚਿਆਂ ਨੂੰ ਬਿਲਡਿੰਗ ਵਿੱਚੋਂ ਸੁਰੱਖਿਅਤ ਬਾਹਰ ਕੱਢਣਾ ਅਤੇ ਸਬੰਧਿਤ ਵਿਭਾਗ ਨਾਲ ਤਾਲਮੇਲ ਕਰਨ ਦੀ ਯੋਜਨਾ ਹੋਣੀ ਚਾਹੀਦੀ ਹੈ। ਸਕੂਲ ਨੂੰ ਇਸ ਯੋਜਨਾ ਦੀ ਪ੍ਰਭਾਵਸ਼ੀਲਤਾ ਨੂੰ ਯਕੀਨੀ ਬਣਾਉਣ ਲਈ ਨਿਯਮਿਤ ਤੌਰ ਤੇ ਸਮੀਖਿਆ ਅਤੇ ਅਪਡੇਟ ਕਰਦੇ ਰਹਿਣਾ ਚਾਹੀਦਾ ਹੈ।
2. ਜੇਕਰ ਸਕੂਲ ਵੱਲੋਂ ਇਸ ਇਮਾਰਤ ਵਿੱਚ ਕੋਈ ਵਾਧਾ, ਤਬਦੀਲੀ, ਵਿਸਤਾਰ ਅਤੇ ਸੋਧ ਦੀ ਲੋੜ ਹੈ ਜਾਂ ਕੀਤੇ ਜਾਣੇ ਹਨ ਤਾਂ ਇਸ ਦਫ਼ਤਰ ਨੂੰ ਤਰੱਤ ਜਾਂਚ ਦਾ ਪ੍ਰਬੰਧ ਕੀਤੀ ਜਾਣਾ ਚਾਹੀਦਾ ਹੈ ਅਤੇ ਉਸ ਹਿੱਸੇ ਨੂੰ ਮੁਕੰਮਲ ਕਰਕੇ ਉਸਦਾ ਸੇਫਟੀ ਸਰਟੀਫਿਕੇਟ ਇਸ ਦਫ਼ਤਰ ਪਾਸੋਂ ਫਿਰ ਤੋਂ ਲਿਆ ਜਾਵੇ।
3. ਜੇਕਰ ਬਿਲਡਿੰਗ ਦੀਆਂ ਕੰਧਾਂ, ਨੀਂਹਾਂ ਅਤੇ ਛੱਤਾਂ ਕੁਦਰਤੀ ਆਫ਼ਤ ਜਾਂ ਕਿਸੇ ਹੋਰ ਕਾਰਨ ਕਰਕੇ ਬੈਠ ਜਾਣ ਤਾਂ ਇਸ ਸੂਰਤ ਵਿੱਚ ਸਕੂਲ ਵੱਲੋਂ ਇਸ ਦਫ਼ਤਰ ਨੂੰ ਤਰੱਤ ਬਿਲਡਿੰਗ ਦੀ ਹਾਲਤ ਬਾਰੇ ਸੂਚਿਤ ਕੀਤਾ ਜਾਵੇ ਅਤੇ ਨਿਰੀਖਣ ਕਰਵਾਉਣ ਉਪਰੰਤ ਹੀ ਬਿਲਡਿੰਗ ਨੂੰ ਵਰਤੋਂ ਵਿੱਚ ਲਿਆ ਜਾਵੇ।
4. ਸਬੰਧਿਤ ਵਿਭਾਗ ਤੋਂ ਵੱਖਰੇ ਤੌਰ ਤੇ ਫਾਇਰ ਸੇਫਟੀ ਅਤੇ ਇਲੈਕਟ੍ਰੀਕਲ ਸੇਫਟੀ ਸਰਟੀਫਿਕੇਟ ਪ੍ਰਾਪਤ ਕੀਤਾ ਜਾਵੇ।
5. ਸਕੂਲ ਬਿਲਡਿੰਗ ਦੀ ਸੇਫਟੀ ਨੂੰ ਮੁੱਖ ਰੱਖਦੇ ਹੋਏ ਬਿਲਡਿੰਗ ਦੀ ਰਿਪੋਰਟ ਕਰਵਾਉਣ ਦੀ ਜ਼ਿੰਮੇਵਾਰੀ ਸਕੂਲ ਪ੍ਰਬੰਧਨ ਦੀ ਹੈ। ਇਸ ਰਿਪੋਰਟ ਦੇ ਬਾਵਜੂਦ ਸਕੂਲ ਪ੍ਰਬੰਧਨ ਸਾਰੇ ਪੱਖਾਂ ਤੋਂ ਬਿਲਡਿੰਗ ਦੀ ਸੁਰੱਖਿਆ ਲਈ ਜ਼ਿੰਮੇਵਾਰ ਹੈ।
6. Er. Anuj Gupta ਵੱਲੋਂ ਮਿਤੀ 01.09.2022 ਨੂੰ ਸਟਰੱਕਚਰ ਸੁਰੱਖਿਆ ਸਰਟੀਫਿਕੇਟ ਦਿੱਤਾ ਗਿਆ ਹੈ ਅਤੇ ਉਹਨਾਂ ਦੇ ਸਰਟੀਫਿਕੇਟ ਅਨੁਸਾਰ ਸਕੂਲ ਸੈਸ਼ਨ 2024-25 ਲਈ ਵਰਤੋਂ ਲਈ ਸੁਰੱਖਿਅਤ ਹੈ, ਪਰੰਤੂ ਇਸ ਸਕੂਲ ਦਾ ਨਿਰਮਾਣ ਇਸ ਵਿਭਾਗ ਵੱਲੋਂ ਨਹੀਂ ਕੀਤਾ ਗਿਆ ਹੈ, ਇਸ ਲਈ ਇਸ ਵਿਭਾਗ ਦੁਆਰਾ ਸਕੂਲ ਦੀ ਸਟਰੱਕਚਰ ਸੇਫਟੀ ਖਾਸ ਕਰਕੇ ਭੂਚਾਲ ਦੇ ਦ੍ਰਿਸ਼ਟੀਕੋਣ ਤੋਂ ਯਕੀਨੀ ਨਹੀਂ ਬਣਾਈ ਜਾ ਸਕਦੀ ਹੈ।
7. ਸਕੂਲ ਨੂੰ ਸਟਾਫ ਮੈਂਬਰਾਂ ਨੂੰ ਉਚਿਤ ਸੁਰੱਖਿਆ ਸਿਖਲਾਈ ਪ੍ਰਦਾਨ ਕਰਨੀ ਚਾਹੀਦੀ ਹੈ, ਜਿਸ ਵਿੱਚ ਐਮਰਜੈਂਸੀ, ਫਸਟ ਏਡ ਅਤੇ ਨਿਕਾਸੀ ਪ੍ਰੋਟੋਕੋਲ ਨੂੰ ਸੰਭਾਲਣ ਦੀਆਂ ਪ੍ਰਕਿਰਿਆਵਾਂ ਵੀ ਸ਼ਾਮਿਲ ਹਨ।
8. ਸਕੂਲ ਦੇ ਕਵਰਡ ਏਰੀਏ ਦੇ ਹਿਸਾਬ ਨਾਲ ਜੀ.ਆਰ. ਨੰਬਰ 16084034 ਮਿਤੀ 14.02.2025 ਰਾਹੀਂ ਦਸ ਹਜ਼ਾਰ ਰੁਪਏ (10,000) ਬਿਲਡਿੰਗ ਨਿਰੀਖਣ ਫੀਸ ਵੱਜੋਂ ਪ੍ਰਾਪਤ ਕੀਤੇ। ਸਕੂਲ ਦਾ ਫਾਇਰ ਸੇਫਟੀ ਸਰਟੀਫਿਕੇਟ 04.08.2025 ਤੱਕ ਵੈਲਿਡ ਹੈ ਅਤੇ ਸਕੂਲ ਪ੍ਰਬੰਧਨ ਸਮੇਂ ਸੀਮਾਂ ਅੰਦਰ ਫਾਇਰ ਸਰਟੀਫਿਕੇਟ ਰੀਨਿਊ ਕਰਵਾਉਣ ਲਈ ਜ਼ਿੰਮੇਵਾਰ ਹੋਵੇਗਾ।
9. ਇਸ ਪੱਤਰ/ਸਰਟੀਫਿਕੇਟ ਦਾ ਸਕੂਲ ਦੀ ਜਗ੍ਹਾ ਦੀ ਮਲਕੀਅਤ ਨਾਲ ਕੋਈ ਸਬੰਧ ਨਹੀਂ ਹੈ।
10. ਇਸ ਪੱਤਰ/ਸਰਟੀਫਿਕੇਟ ਦਾ ਸਕੂਲ ਦੇ ਪਲਾਟ ਏਰੀਏ ਦਾ ਕੋਈ ਸਬੰਧ ਨਹੀਂ ਹੈ।
11. ਇਸ ਮਨਜ਼ੂਰੀ ਦਾ ਸਿਡਿਊਲਡ ਰੋਡ ਐਕਟ ਨਾਲ ਕੋਈ ਸਬੰਧ ਨਹੀਂ ਹੈ।
12. ਇਹ ਰਿਪੋਰਟ ਕਾਨੂੰਨੀ ਉਦੇਸ਼ ਲਈ ਵੈਲਿਡ ਨਹੀਂ ਹੈ।

ਨੱਥੀ/ ਸਰਟੀਫਿਕੇਟ

ਪਿੱਠ ਅੰਕਣ ਨੰ:

ਕਾਰਜਕਾਰੀ ਇੰਜੀਨੀਅਰ,  
ਪ੍ਰਾਂਤਕ ਮੰਡਲ ਭਤੇਮ ਸ਼ਾਖਾ,  
ਫ਼ਰੀਦਕੋਟ।  
ਮਿਤੀ:

PROFORMA FOR SAFETY OF SCHOOL BUILDING

PART-1

(To be filled by head of School/Institute)

1. Name of the School **P.S.T MEMORIAL PUBLIC SCHOOL GHUDUWALA**
2. Location **JAND SAHIB ROAD GHUDUWALA FARIDKOT**
3. Plot Area **3.50 Acres.**
4. Plinth Area **G.F- 21773 FT. F.F- 12349 FT. TOTAL- 34122**
5. Number of Storey **TWO**
6. Year of Construction of Building **G.F- 2010, F.F- 2011 & 2014**
7. If the building has been constructed under the supervision of the qualified Engineer, the following details may be given
  - a) Name of the Engineer with qualification **PUNEET RAMPAL, DIPLOMA IN CIVIL**
  - b) Address of Engineer **SHOP NO-42, NEHRU SHOPPING CENTRE, FARIDKOT**
  - c) Set of Structural drawings used in the construction if available
  - d) Name & Address of the architect with qualification
8. Whether the building has been constructed for the purpose of
  - a) School **Yes/No** ✓
  - b) Residential purpose and converted for use as a School **Yes/No** ✓
9. Materials used for roofs
  - a) R.C.C Slabs/RBC Slabs **Yes/No** ✓
  - b) R.S joists & Battons **Yes/No** ✓
  - c) Wooden joists & Battons **Yes/No** ✓
10. Materials used for walls
  - a) Mud Mortar **Yes/No** ✓
  - b) Cement Mortar **Yes/No** ✓
  - c) Lime mortar **Yes/No** ✓
11. Flooring
  - a) Congremerate **Yes/No** ✓
  - b) Terrazzo **Yes/No** ✓
  - c) Brick Paving **Yes/No** ✓
12. A detailed drawing indicating dimensions of the rooms, Along with size and location of doors and window (Attached) **Yes/No**
13. FOR FIRE SAFETY
  - a) Whether the width of the staircase is Mtr. **Yes/No**
  - b) Whether Portable fire extinguisher exists **Yes/No**
  - c) Whether School building is Free from inflammable & toxic material **Yes/No**
  - d) Whether cooking of food is done at a safe place **Yes/No**
  - e) Whether any Thatch or combustible material has been used **Yes/No**
14. Requirement for fire Protection Arrangements under NBC Part IV (For building height less than 15 meter)
  - a) Whether house real provided **Yes/No**

Fire safety certificate is attached

- d) Whether over head tank of capacity 10000 Ltrs. Exists (in case of house real 20000-Lt. Yes/No
- e) Whether on electric and one diesel pump of 3kg/ Cum pressure of capacity 1620 LPM one electric Pump of capacity 180 LPM exist near underground static tank. Yes/No
- f) Whether a Pump 3 kg/ cum pressure & 450/500 LPM exists near over head tank Yes/No

Signature with Stamp seal of the School/Institution




PART-II

Building Safety Report

Name of School P. S-T MEMORIAL PUBLIC SCHOOL  
GHUDUWALA (FARIDKOT.)

Junior Engineer.. Sh. Baldev Singh..... have visited the above mentioned school building on 14-02-2025.....and on visually inspection, it Seems visually safe subject the following observation & conditions.

- a) Parameters to check the stability and safety of building such as Architectural Drawings, Bearing capacity, Foundation detail, Structural Drawings, Technical Specifications, Test Reports of Material used, Quality control Reports and certificate from the Engineer In Charges for construction are not available.
- b) In case any addition or expansion and modification to this building are done, Certificate may be re-obtained after the completion from the undersigned.
- c) In case the building is affected by flood or if there is any settlement walls/foundation or sagging of roofs etc, immediate inspection of the undersigned be arranged to check stability and safety of the Building.
- d) A separate certificate regarding Fire Fighting should be obtained from the competent Authority
- e) A separate certificate regarding Electrical works should be obtained from the competent authority.
- f) The owner of the building/Management is fully responsible regarding safety of the building from all angles in spite of this report.
- g) The covered area of the building is 341.22.00..... Sft.
- h) This report is not valid for legal purpose.
- i) The building visually seems safe to occupy for normal use up to 31.03.2025..... under normal circumstances & conditions.

  
Sub Divisional Engineer,